

2 / 3




FIG. 3




FIG. 4

ROTARY PISTON VACUUM PUMP WITH WASHING INSTALLATION
Mark Christopher Hope, Clive Marcus Lloyd Tunna, Frederick John Underwood
Serial No. 10/531,563
Dkt. No. M02B155
REPLACEMENT SHEET




Figure 5

FIGURE 6




FIGURE 7




FIGURE 8




FIGURE 9





FIGURE 10



(Prior Art)